

FIRMWARE UPDATE

Version 4.6

FD100 Diesel Controllers

Version 4.6 has been released and is now installed on all FD100 Series of Diesel Fire Pump Controllers.

These changes were made in response to customer feedback.

Changes Include:

Status Report "Quick" Button

You can now print the status report without having to go through the whole menu system
To do this press and hold the F3 button for three (3) seconds

Mode Change Recording

The controller will now sense when the user has switched from one mode to the next
This enhances the controller's troubleshooting abilities

Stop Pushbutton

The Stop Pushbutton is now active when the controller is programmed for Automatic Stop
Please keep in mind that it will only stop the controller once a 15 second time delay has elapsed and all starting conditions have been returned to normal (the system pressure has to be above the programmed Pressure Stop Point)

AC Power Failure

The controller will now record when the AC Power has been restored to the controller
You will see the message "AC Power OK"

Version 4.6 has been installed on all FD100 Diesel controllers - effective August 15, 2001.